


FRAX clamps and connections

FRAX Application Note 2016-03-31

FRAX C-clamp GC-80010

C-LAMP - Generator & Measure
Signal: BNC center connector, entire
clamp including strain relief holder.

GROUND
Ground screw
BNC housing



Megger[®]

FRAX C-clamp - How to connect!


Ground braid from ground screw, straight down the bushing to the nearest ground at the bottom of the bushing (small ground connection c-clamp). Good braid-to-ground connection is essential for repeatable measurements at higher frequencies (< 500 kHz).

Connect FRAX cables to BNC connectors and make sure to use the strain relief correctly to avoid unnecessary loading/wear on BNC cable and connectors.



FRAX Clamp & Cables – Generator fault


Short circuit between generator signal and ground.
Strain relief in contact with BNC ground via snap hook.



Megger[®]


FRAX Clamp & Cables – Generator fault

Short circuit between bushing/generator signal and ground braid.



Megger[®]


Generator fault - Results



BNC connector fault – Short circuit


Additional information:

A possible cable problem is a short circuit between center lead and shield, which is the same as clamp being short circuited to ground. Same faulty curves appear as in the examples.



FRAX Clamp & Cables – Measure fault

Short circuit between measure signal and ground.



Megger[®]


FRAX Clamps & Cables – Measure fault

Short circuit between bushing/generator signal and ground braid.



Megger[®]

FRAX Clamps & Cables – Measure example




FRAX C-clamp & Cables – No connection

Additional information:


Disconnected cable can also be a broken cable where there is no connection between BNC center and center conductor of cable. This easy to check. Use a std ohm-meter and check that you have a good connection between BNC center conductors.

The same symptoms will appear if the C-clamp has a broken connection between BNC center and clamp. This is very unusual but easy to check. Use a std ohm-meter and check that you have a connection between clamp and BNC center conductor.


Examples of faulty curves, see the following examples.



FRAX connections – Not connected faults



FRAX connections – Not connected faults



FRAX connections – Not connected faults

